APPENDIX E: PHOTO LOG

In support of AECOM's efforts to document observations related to identifying potential human uses of and exposures to the LPRSA, photographs were taken to document pertinent features. As presented in the LPRSA Human Access/Exposure Identification Survey Form, which is in Attachment T of the Benthic QAPP Addendum No. 3 (Windward 2010),[1] these may include:

- The presence of fencing, buildings, infrastructure, or other features that may affect access
- Characteristics of shoreline and intertidal areas
- Shoreline features, such as parks/green space, docks, boat ramps, benches, or other amenities
- Evidence of human use or activities (e.g., boating, fishing), established paths, trails to or along the shoreline, abutting residential properties with steps/access to shoreline

As such, this photographic log serves to illustrate features relevant to human use of the LPRSA but does not necessarily reflect the habitat of the Study Area.

[1] Windward. 2010. Lower Passaic River Restoration Project. Lower Passaic River Study Area RI/FS. Habitat identification survey: Addendum to the Quality Assurance Project Plan. Surface sediment chemical analyses and benthic invertebrate toxicity and bioaccumulation testing. Addendum No. 3. Final. Prepared for Cooperating Parties Group, Newark, New Jersey. September 13, 2010. Windward Environmental LLC, Seattle, WA.

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
1	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 0.2
Passaic Valley Sewer Sewerage Commission dock

Photo No.	Date:
2	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 0.5
Port area

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
3	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 0.6
Boat dock adjacent to bulkhead pier

Photo No.	Date:
4	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 1.5
Industrial properties

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
5	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 2.4
I-95 Bridge

Photo No.	Date:
6	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 2.6

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
7	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 2.8

Photo No.	Date:
8	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 2.9
Shipping containers along bulkhead

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
9	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 3.0
Bulkhead along 80 Lister Avenue site

Photo No.	Date:
10	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 3.5

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
11	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 4.2
Homeless camp

Photo No.	Date:
12	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 5.0
Open space with Newark in background



PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
13	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 5.0
Open space with Newark in background

Photo No.	Date:
14	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 5.1
Open space with Newark in background

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
15	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 5.4

Photo No.	Date:
16	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 5.6
I-280 Bridge

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
17	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 5.5

Photo No.	Date:
18	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 6.5

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No. 19 | **Date:** 09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 6.5

Photo No. 20 | **Date:** 09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 7.1
Private Boat Dock and Marina

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
21	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 7.5
Route 21

Photo No.	Date:
22	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 8.6
Route 7 Bridge

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:	
23	09/20/10	
Direction Photo Taken: Left (West) Bank		
Description: RM 8.7		

Photo No.	Date:	
24	09/20/10	
Direction Photo Taken: Left (West) Bank		
Description: RM 8.8		

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
25	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 9.7

Photo No.	Date:
26	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 10.4
Homeless camp

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
27	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 10.5
Nutley Boat Ramp

Photo No.	Date:
28	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 11.6

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No. 29 | **Date:** 09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 11.7

Photo No. 30 | **Date:** 09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 12.5
Private boat ramp

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No. 31 | **Date:** 09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 12.7

Photo No. 32 | **Date:** 09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 12.8
Fishing observed

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
33	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 14.0

Photo No.	Date:
34	09/20/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 14.0

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
35	09/21/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 14.2
Homeless camp under the Dundee Canal Bridge

Photo No.	Date:
36	

Direction Photo Taken:

Left (West) Bank

Description:

RM 14.3

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
37	09/21/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 14.5



Photo No.	Date:
38	

Direction Photo Taken:

Left (West) Bank

Description:

RM 14.8

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No. 39 | **Date:** 09/21/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 14.9



Photo No. 40 | **Date:** 09/21/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 15.4
Boat Ramp

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No. 41 | **Date:** 09/21/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 15.5
Private boat ramp

Photo No. 42 | **Date:**

Direction Photo Taken:

Left (West) Bank

Description:

RM 15.9
Pulaski Park Boat Ramp



PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No. 43 | **Date:** 09/21/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 16.0
Pulaski Park



Photo No. 44 | **Date:** 09/21/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 16.1

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No. 45 | **Date:** 09/21/10

Direction Photo Taken:

Left (West) Bank

Description:

RM 16.1
Parkland

Photo No. 46 | **Date:**

Direction Photo Taken:

Left (West) Bank

Description:

RM 16.2
Parkland

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
47	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 17.1
(On land)
Fishing observed

Photo No.	Date:
48	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 17.1
(On land)
Debris from homeless camp

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
49	09/20/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 0.4
Kearny Point

Photo No.	Date:
50	09/20/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 1.5

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
51	09/20/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 1.9

Photo No.	Date:
52	09/20/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 2.2

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
53	09/20/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 2.3

Photo No.	Date:
54	09/20/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 4.0

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
55	09/20/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 4.1

Photo No.	Date:
56	09/20/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 5.0

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
57	09/20/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 5.5

Photo No.	Date:
58	09/20/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 5.5
Hampton Inn

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:	
59	09/20/10	

Direction Photo Taken:

Right (East) Bank

Description:

RM 5.6

Photo No.	Date:	
60	09/20/10	

Direction Photo Taken:

Right (East) Bank

Description:

RM 6.5

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
61	09/20/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 6.6
Pathmark/Marshalls pier

Photo No.	Date:
62	09/20/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 6.7
Kearny Car Wash

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
63	09/20/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 6.8
Kearny Boat Launch at Riverbank Park

Photo No.	Date:
64	09/20/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 7.4
Riverbank Park

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
65	09/20/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 7.7
Rapp's Boat Yard

Photo No.	Date:
66	09/20/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 7.7
Riverbank Park
(On land)

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
67	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 8.5
Kearny High School Crew Floating Dock

Photo No.	Date:
68	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 8.5
Northern end of Riverbank Park

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No. 69 | **Date:** 09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 8.8
Baseball field

Photo No. 70 | **Date:** 09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 9.0
Private boat dock

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
71	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 9.1
Firehouse Boat Launch

Photo No.	Date:
72	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 9.1
Fishing observed next to firehouse

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
73	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 9.1
Parkland

Photo No.	Date:
74	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 9.5
Passaic Valley Sewer Commission Private Boat Launch

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
75	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 9.6
Aquatic vegetation/mudflat near power lines

Photo No.	Date:
76	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 9.6
Riverside County Park

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
77	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 9.6
Riverside County Park
(On land)

Photo No.	Date:
78	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 9.7
Riverside County Park

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
79	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 9.9
Passaic River Rowing Association Boathouse and Dock

Photo No.	Date:
80	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 10.3
Multifamily Residential Building and Bulkheaded Shoreline

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
81	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 10.5
Riverside County Park

Photo No.	Date:
82	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 10.7
Riverside County Park

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
83	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 11.0
Lyndt Park
Boat Launch

Photo No.	Date:
84	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 11.6
Montclair College Boathouse and Dock

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
85	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 11.8
Private boat launch

Photo No.	Date:
86	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 11.8
Private boat dock

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
87	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 11.9
Residential

Photo No.	Date:
88	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 12.1
Nereid Boat Club

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
89	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 12.3
Residential

Photo No.	Date:
90	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 12.6
Residential

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
91	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 12.7
Residential

Photo No.	Date:
92	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 12.7
Residential

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
93	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 12.8
Private dock in residential area

Photo No.	Date:
94	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 13.4
Rutherford Memorial Park

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
95	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 13.4
CPG Dock

Photo No.	Date:
96	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 13.8
Memorial Park
(On land)

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No. 97 | **Date:** 09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 14.0
Residential

Photo No. 98 | **Date:** 09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 14.3
Boat Ramp

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
99	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 14.3
Residential



Photo No.	Date:
100	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 14.5

PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No. 101 | **Date:** 09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 14.6
Boat Ramp

Photo No. 102 | **Date:** 09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 15.2
Residential



PHOTOGRAPHIC LOG

Site Name:	Site Location:	Project No.
Lower Passaic River Restoration Project	Lower Passaic River Study Area, NJ	60145884

Photo No.	Date:
103	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 15.5
Confluence with Saddle River



Photo No.	Date:
104	09/21/10

Direction Photo Taken:

Right (East) Bank

Description:

RM 15.6